

## KATALOG HLINÍKOVÝCH PROFILŮ

| Profil /mm/                | Číslo profilu | Profil /mm/                        | Číslo profilu | Profil /mm/   | Číslo profilu |
|----------------------------|---------------|------------------------------------|---------------|---|---------------|
| <b>Jekl čtvercový</b>      |               | <b>L Profil</b>                    |               | <b>Trubky</b>   |               |
| 15 x 15 x 1,5              | D-UM-300001   | 15 x 10 x 2,0                      | PBM-300043    | 25 x 2,0  | PBM-300042    |
| 15 x 15 x 2,0              | PBM-300001    | 15 x 15 x 2,0                      | UPBM-0007     | 28 x 2,0  | UPBM-0015     |
| 20 x 20 x 1,5              | PBM-300075    | 20 x 10 x 2,0                      | PBM-300054    | 30 x 2,0  | PBM-300046    |
| 20 x 20 x 2,0              | PBM-300058    | 20 x 15 x 2,0                      | PBM-300004    | 32 x 2,0  | UPBM-0002     |
| 25 x 25 x 1,5              | PBM-300071    | 20 x 20 x 2,0                      | PBM-300026    | 32 x 2,0 <b>d.3M</b>  | UPM300008     |
| 25 x 25 x 2,0              | UPBM-0014     | 20 x 20 x 3,0                      | PBM-300079    | 40 x 2,0  | 8-JM-320012   |
| 30 x 30 x 2,0              | UPBM-0017     | 25 x 25 x 2,0                      | PBM-300016    | 45 x 2,0  | PBM300078     |
| 30 x 30 x 3,0              | PBM-300050    | 30 x 15 x 2,0                      | PBM-300015    | 45 x 3,0  | PBM300090     |
| 35 x 35 x 2,0              | UPBM-0016     | 30 x 20 x 2,0                      | UPBM-0020     | 48 x 3,0  | PBM-300033    |
| 40 x 40 x 2,0              | UPBM-0009     | 30 x 30 x 2,0                      | UPBM-0025     | 50 x 2,0  | PBM-300077    |
| 40 x 40 x 3,0              | PBM-300064    | 35 x 35 x 2,0                      | PBM-300030    | <b>Jekl fáborek</b>   |               |
| 40 x 40 x 4,0              | PBM-300060    | 40 x 20 x 2,0                      | PBM-300052    | 50 x 30 x 30 x 2 jednostr.  | K-PM-310001   |
| 50 x 50 x 2,0              | UPBM-0018     | 40 x 30 x 2,0                      | PBM-300005    | 70 x 50 x 30 x 2 jednostr.  | K-PM-310003   |
| 50 x 50 x 3,0              | PBM-300029    | 40 x 40 x 2,0                      | UPBM-0022     | 70 x 30 x 30 x 2 oboustr.   | K-PM-310002   |
| 50 x 50 x 4,0              | PBM300087     | 40 x 40 x 3,0                      | PBM-300006    | 90 x 50 x 30 x 2 oboustr.   | K-PM-310004   |
| 60 x 60 x 2,0              | PBM-300044    | 40 x 40 x 4,0                      | PBM-300021    | <b>Výkresové profily</b>  |               |
| 60 x 60 x 3,0              | PBM-300018    | 40 x 40 x 5,0                      | PBM-300003    | T profil 30 x 30 x 3,0  | PBM-300040    |
| 60 x 60 x 4,0              | PBM300092     | 50 x 30 x 2,0                      | UPBM-0001     | <b>Eloxované profily</b>  |               |
| 80 x 80 x 2,0              | PBM-300068    | 50 x 50 x 2,0                      | UPBM-0008     | ■ L profil 15 x 10 x 2,0  | C-PM-300007   |
| 80 x 80 x 3,0              | PBM300108     | 50 x 50 x 3,0                      | PBM-300012    | ■ L profil 15 x 15 x 2,0  | C-PM-300008   |
| 80 x 80 x 4,0              | PBM-300059    | 50 x 50 x 5,0                      | PBM-300032    | ■ Lprofil 20 x 20 x 1,5   | C-PM-300009   |
| 100 x 100 x 2,0            | UPBM-0005     | 60 x 30 x 2,0                      | PBM-170001    | ■ Lprofil 20 x 20 x 2,0   | C-PM-300011   |
| 100 x 100 x 3,0            | PBM-300009    | 60 x 30 x 3,0                      | PBM-300039    | ■ L profil 25 x 25 x 2,0  | C-PM-300005   |
| 100 x 100 x 5,0            | C-PM-300001   | 60 x 40 x 3,0                      | PBM-300017    | ■ L profil 30 x 15 x 2,0  | C-PM-300006   |
| <b>Jekl obdélníkový</b>    |               | 60 x 40 x 5,0                      | PBM300088     | ■ L profil 30 x 30 x 1,5  | C-PM-300010   |
| 20 x 10 x 1,5              | PBM-300069    | 60 x 60 x 2,0                      | UPBM-0003     | ■ L profil 30 x 30 x 2,0  | C-PM-300012   |
| 20 x 10 x 2,0              | PBM-300031    | 80 x 30 x 3,0                      | PBM-300038    | ■ L profil 40 x 20 x 2,0  | C-PM-300004   |
| 20 x 15 x 2,0              | PBM-300074    | 80 x 80 x 5,0                      | PBM300103     | <b>Standardně vedeme profily skladem:</b>                               |               |
| 25 x 15 x 2,0              | UPBM-0012     | 100 x 30 x 3,0                     | 5-ZBM160077   | v délkách 6000 mm   |               |
| 25 x 20 x 2,0              | TEST-0068     | 100 x 50 x 3,0                     | PBM300107     | ■ v délkách 6100 mm   |               |
| 30 x 15 x 2,0              | UPBM-0021     | 100 x 50 x 5,0                     | PBM-300007    | <b>Plocháč</b>  |               |
| 30 x 20 x 2,0              | PBM-300062    | 20 x 3,0                           | PBM-300053    | <b>Materiál: EN AW-6060 T66</b>   |               |
| 30 x 25 x 2,0              | PBM-300072    | 20 x 5,0                           | PBM-300035    | <b>Materiál: EN AW-6082 T6</b>  |               |
| 40 x 15 x 2,0              | PBM-300061    | 30 x 2,0                           | PBM300106     | Profily dělíme na míru a řežeme pod úhlem.                              |               |
| 40 x 20 x 2,0              | UPBM-0013     | 30 x 3,0                           | PBM00105      | Nabízíme možnost výroby a dodávek                                       |               |
| 40 x 20 x 3,0              | PBM300102     | 30 x 5,0                           | PBM300109     | standardních i výkresových profilů.                                     |               |
| 40 x 25 x 2,0              | PBM300091     | 30 x 6,0                           | PBM-300076    | Kompletní nabídku dodávaných profilů                                    |               |
| 40 x 30 x 2,0              | PBM-300014    | 40 x 2,0                           | PBM-300002    | naleznete v katalogu <a href="http://www.keramet.cz">www.keramet.cz</a> |               |
| 50 x 20 x 2,0              | UPBM-0026     | 40 x 4,0                           | PBM-300056    |   |               |
| 50 x 25 x 2,0              | PBM-300073    | 40 x 4,0                           | PBM300093     |   |               |
| 50 x 30 x 2,0              | UPBM-0019     | 40 x 5,0                           | PBM300081     |   |               |
| 50 x 40 x 2,0              | UPBM-0006     | 50 x 3,0                           | PBM-300051    |   |               |
| 60 x 20 x 2,0              | UPBM-0011     | 50 x 5,0                           | PBM-300055    |   |               |
| 60 x 30 x 2,0              | UPBM-0010     | 50 x 5,0                           | PBM300094     |   |               |
| 60 x 30 x 2,0 <b>R3</b>    | PBM300095     | <b>U Profily</b>                   |               |   |               |
| 60 x 30 x 3,0              | PBM-300066    | U 10 x 10 x 10 x 2,0               | PBM-300022    |   |               |
| 60 x 40 x 2,0              | PBM-300020    | U 15 x 10 x 15 x 1,5               | PBM300082     |   |               |
| 60 x 40 x 3,0              | PBM-300010    | U 15 x 15 x 15 x 2,0               | PBM-300037    |   |               |
| 60 x 40 x 3,0 <b>d.7M</b>  | PBM300100     | U 15 x 30 x 15 x 3,0               | 5-ZBM160023   |   |               |
| 60 x 40 x 4,0              | PBM-300025    | U 20 x 20 x 20 x 2,0               | PBM300097     |   |               |
| 80 x 20 x 2,0              | PBM-300063    | U 20 x 30 x 20 x 2,0               | PBM-300048    |   |               |
| 80 x 30 x 2,0              | UPBM-0023     | U 20 x 40 x 20 x 2,0               | PBM-300041    |   |               |
| 80 x 40 x 2,0              | UPBM-0004     | U 25 x 25 x 25 x 2,0               | PBM300080     |   |               |
| 80 x 40 x 4,0              | PBM-300070    | U 30 x 25 x 30 x 2,0               | PBM300104     |   |               |
| 80 x 60 x 3,0              | PBM-300067    | U 30 x 30 x 30 x 2,0 <b>d.4,5M</b> | PBM300110     |   |               |
| 100 x 20 x 2,0             | PBM-300011    | U 30 x 30 x 30 x 2,0               | PBM-300019    |   |               |
| 100 x 40 x 2,0             | PBM-300013    | U 40 x 40 x 40 x 2,0               | PBM300101     |   |               |
| 100 x 50 x 2,0             | PBM-300024    | U 40 x 80 x 40 x 4,0               | C-PM-300003   |   |               |
| 100 x 50 x 2,0 <b>d.7M</b> | ZPBM-0003     | U 50 x 50 x 50 x 3,0               | PBM300098     |   |               |
| 100 x 50 x 3,0             | ZPBM-0001     | U 50 x 100 x 50 x 3,0              | PBM300089     |   |               |
| 100 x 50 x 3,0 <b>d.7M</b> | ZPBM-0001     |                                    |               |   |               |
| 120 x 20 x 2,0             | UPBM-0024     |                                    |               |   |               |
| 120 x 40 x 2,0             | ZPBM-0010     |                                    |               |   |               |
| 120 x 40 x 4,0             | ZPBM-0002     |                                    |               |   |               |
| 120 x 50 x 3,0             | ZPBM-0004     |                                    |               |   |               |
| 140 x 20 x 3,0             | ZPBM-0011     |                                    |               |   |               |
| 150 x 20 x 2,0             | 5-ZM200004    |                                    |               |   |               |
| 150 x 40 x 2,5             | 5-ZM200003    |                                    |               |   |               |
| 150 x 40 x 4,0             | PBM300096     |                                    |               |   |               |
| 150 x 50 x 4,0             | ZPBM-0012     |                                    |               |   |               |
| 200 x 50 x 4,0             | 8-JM-320012   |                                    |               |   |               |

Aktualizace: 02/2021